

3D LASER CUT MODELS






It is highly recommended that you visit www.fascinations.com/metalearth360/mms323 to see the completed model before assembling your own







Metal sheets

To create the best connections

inserted

and then


folded




Insert tab and bend 90 degrees for most visible areas



Insert tab and twist 90 degrees is best in some areas to ensure a tight connection








In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

be seen

as shown

here



Assembly Flow Chart

