

# The Leaning Tower of Pisa


**ICONX**  
3D METAL MODEL KITS



It is highly recommended that you visit [www.fascinations.com/iconx360/iconx015](http://www.fascinations.com/iconx360/iconx015) to see the completed model before assembling your own

FASCINATIONS, INC.  
Seattle, Washington, USA

ICX015




## TO CREATE THE BEST CONNECTIONS


● Insert tab into slot and bend 90 degrees



▲ Insert tab into slot and twist 90 degrees



## METAL SHEET




**⚠** In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed.


Go to [www.fascinations.com/iconx360/iconx015](http://www.fascinations.com/iconx360/iconx015) to see the zoomable PDF version of this instruction sheet

## ASSEMBLY STEPS


### Step 1




### Step 2




### Step 3




### Step 4




### Step 5



### Step 6



### Step 7



### Step 8

