


METAL EARTH™


3D LASER CUT MODELS



It is highly recommended that you visit
www.fascinations.com/metalearth360/mms321
 to see the completed model before assembling your own




mms321



Insertion tabs are inserted and then folded

Insertion holes

Fold lines can be seen as shown here




Needle nose pliers are helpful for assembly

Metal sheet



To create the best connections

● Insert tab and bend 90 degrees for most visible areas

▲ Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed



Assembly Flow Chart

