METALEARTH

3D LASER CUT MODELS





It is highly recommended that you visit


www.fascinations.com/metalearth360/mms010

to see the completed model before assembling your own









Insertion tabs are inserted and then folded Fold lines can be seen as shown

Insertion holes


To create the best connections




Insert tab and bend 90 degrees for most visible areas



Insert tab and twist 90 degrees is best in some areas to ensure a tight connection







In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

