

# METAL EARTH™

## 3D LASER CUT MODELS



It is highly recommended that you visit [www.fascinations.com/metalearth360/mms266](http://www.fascinations.com/metalearth360/mms266) to see the completed model before assembling your own




mms266


### To create the best connections

Insert tab and bend 90 degrees for most visible areas

Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



Needle nose pliers are helpful for assembly




Pull and Screw metal tab 90° to tighten

Insertion tabs are inserted and then folded

Fold lines can be seen as shown here

Insertion holes

### Metal sheets



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

### Assembly Flow Chart

